

		IB Switches			
<u>OS & Platforms</u>	<u>IB PCI HCA</u>	Sun 9P IB Switch	Topspin 360/90	Voltaire 9096	SilverStorm 9024
X64(S10 U1)					
SF V20z/V40z	PCI-X	Yes	Yes	Yes	Yes
SF X2100	PCI-E	Yes	Yes	Yes	Yes
SF X4100/X4200	PCI-X	Yes	Yes	Yes	Yes
SB 8000	PCI-E Express Module	Yes	Yes	Yes	Yes
Linux(Mellanox gold CD) RH3.0, RH4.0, Suse9					
SF X2100	PCI-E	Works with turned off	SM N/A	Yes	Yes
SF X4100/X4200	PCI-X	Works with turned off	SM N/A	Yes	Yes
Solaris10+ Solaris10update1					
SF T1000	PCI-E	Yes	-	-	-
SF T2000	PCI-X & PCI-E	Yes	Yes	Yes	Yes
SF V240, SF V440, SF V490, SF V890, SF 1280, SF 2900, SF 4900, SF 6900	PCI-X	Yes	TBD	TBD	TBD
Note:Tested IB-HCA are all Sun brand HCA					

Kernel Version:

RH-3.0 32 bit update-5 = 2.4.21-32.ELsmp

RH-4.0 64 bit update-1 = 2.6.9-11.ELsmp

RH-3.0 64 bit update-5 = 2.4.21-32.ELsmp

SUSE LINUX Enterprise Server 9 sp1 64 bit = 2.6.5-7.139-smp